

-- CEN22FA406 --
WRECKAGE DIAGRAM



-- CEN22FA406 --
Wreckage Distribution
Component Coordinates

Component	Latitude	Longitude
Initial tree strike	35.12614	-84.72678
Wing fragment	35.12626	-84.72679
Wing strut / aileron fragment	35.12628	-84.72676
Rt outboard wing section	35.12624	-84.72670
Rt cabin door	35.12638	-84.72663
Lt horizontal stabilizer fragment	35.12622	-84.72662
Wing fragments	35.12638	-84.72662
Aileron fragment	35.12645	-84.72676
Aileron fragment/lower engine cowling	35.12651	-84.72672
Wing fragment / aileron fragment	35.12650	-84.72654
Rudder fragment / Lt outboard wing fragment	35.12654	-84.72668
Ground impact	35.12654	-84.72665
Engine cylinder fragment	35.12654	-84.72630
Elevator fragment	35.12659	-84.72651
Aileron fragment	35.12642	-84.72663
Lower rudder fragment	35.12664	-84.72647
Lt cabin door fragment	35.12667	-84.72644
Wing fragment / rudder pedal	35.12671	-84.72655
Engine	35.12691	-84.72624
Center/lower fuselage / aft fuselage	35.12717	-84.72634
Engine cylinder / wheel brake caliper	35.12736	-84.72617
Propeller	35.12739	-84.72632

Note: Coordinates recorded by NTSB investigator during on-scene examination.