

CEN22FA433

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the wreckage at the accident site.



Photograph 2 - View of the wreckage at the accident site.



Photograph 3 - View of the engine at the accident site.



Photograph 4 - View of the main rotor mast at the accident site.



Photograph 5 - View of the main rotor blades at the accident site.



Photograph 6 - View of the empennage with fluid spray at the accident site.



Photograph 7 - View of the empennage with fluid spray at the accident site.



Photograph 8 - View of the wreckage laid out at the salvage facility.



Photograph 9 - View of the wreckage laid out at the salvage facility.



Photograph 10 - View of the engine at the salvage facility.