

Carburetor Icing Probability Graph – CEN22LA002

Airplane: Beech A23

Engine: Lycoming O-360-A2G

Fuel: 100 LL

Accident Date: 10/2/2021

Accident Location: Lamesa, TX

Accident Time: 1225 CDT

Weather: METAR KLUV 021735Z AUTO 00000KT 10SM
22/13 A3019 RMK AO2=

Celsius to Fahrenheit Conversion:

Temperature, 22° C = 71.6° F

Dew Point, 13° C = 55.4° F

Source: Federal Aviation Administration

Special Airworthiness Information Bulletin CE-09-35

Carburetor Icing Prevention

