



Photo 1 – Accident Site Overview (Airport Operations Photo)



Photo 2 – Left Wing Damage (Airport Operations Photo)



Photo 3 – Left Main Landing Gear Spring Fracture (FAA Photo)



Photo 4 – Left Main Landing Gear Spring Fracture (FAA Photo)