

Carburetor Icing Probability Graph – CEN22LA010

Airplane: Piper PA24

Engine: Lycoming O-360-A1A

Fuel: 100 LL

Accident Date: 10/7/2021

Accident Location: Fort Collins, CO

Accident Time: 0654 MDT

Weather: METAR KFNL 071256Z 13006KT 10SM CLR
11/04 A3010

Celsius to Fahrenheit Conversion:

Temperature, 11° C = 51.8° F

Dew Point, 4° C = 39.2° F

Source: Federal Aviation Administration

Special Airworthiness Information Bulletin CE-09-35

Carburetor Icing Prevention

