

National Transportation Safety Board

Office of Aviation Safety

Washington, DC 20594



CEN22LA036

THROTTLE CABLE EXAMINATION REPORT

October 31, 2022

TABLE OF CONTENTS

A. ACCIDENT	3
B. THROTTLE CABLE EXAMINATION	3
C. SUMMARY	3
D. DETAILS OF THE EXAMINATION	3
1.0 Throttle Cable Examination	3

A. ACCIDENT

Location: Weatherford, Texas
Date: October 30, 2021
Time: 19:10 (Local)
Airplane: Cessna 177

B. THROTTLE CABLE EXAMINATION REPORT

IIC Jason Aguilera
National Transportation Safety Board
Denver, Colorado

C. SUMMARY

The throttle cable and arm were examined at Air Salvage of Dallas, Lancaster, Texas. Despite accident damage to the engine section that prevented its full range of travel, no anomalies were found that would have precluded its normal operation.

D. DETAILS OF THE EXAMINATION

1.0 Throttle Cable Examination

As part of the airplane engine examination, the throttle cable and its attachment to the carburetor was looked at. Accident damage to the engine section prevented documentation of the throttle cable's full range of travel. The cabling remained properly attached to the carburetor, and no restriction to the throttle arm was noted.

Submitted by:

Jason Aguilera
Senior Air Safety Investigator