



Mitchell Gallo
Senior Aerospace Engineer
Aviation Safety - Central Region

Date: September 8, 2023

Subject: CEN22LA071

Contact: Steve Fowler, President, America's Aircraft Engines, Inc.

Steve Fowler stated that the engine was examined and did not exhibit any component failure. The engine driven fuel pump, which was an experimental fuel pump by Engine Components International, was sent to a fuels shop for testing and that testing showed that the fuel pump provided proper fuel flow rates. He stated that since the engine was provided to America's Aircraft Engines, Inc. by the aircraft owner in 2022, that they had been busy and were able to examine the engine in about the previous week.