

CEN22LA157

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Fuselage during postaccident examination (NTSB Photo)



Photograph 2 - Left wing during postaccident examination (NTSB Photo)



Photograph 3 - Right wing during postaccident examination (NTSB Photo)



Photograph 4 - Engine during postaccident examination (NTSB Photo)



Photograph 5 - No. 8 cylinder during postaccident examination (NTSB Photo)



Photograph 6 - No. 8 piston during postaccident examination (NTSB Photo)



Photograph 7 - Carburetor during postaccident examination (NTSB Photo)