



Photo 1 – Horizontal Stabilizer Damage (Courtesy of South Metro Fire and Rescue)



Photo 2 – Collapsed Landing Gear (Courtesy of South Metro Fire and Rescue)