



Photo 1 – Trunnion damage to right main landing gear - Photo courtesy of Federal Aviation Administration (FAA)



Photo 2 – Bearing found on runway – Courtesy of FAA



Photo 3 – Right wing damage