

CEN22LA186

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damage Overview (Courtesy of FAA)



Photograph 2 - Self Locking Nut (Courtesy of FAA)