

CEN22LA202

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Partially separated elevator (Courtesy of FAA)



Photograph 2 - Right side rudder damage (Courtesy of FAA)



Photograph 3 - Partially separated elevator (Courtesy of FAA)



Photograph 4 - Elevator trim push-pull tube with hardware missing (Courtesy of FAA)