



Photo 1 – Airplane Wreckage at Accident Site (Source: FAA)



Photo 2 – Brake Line Damage Adjacent to the Cutout Hole in the Metal Support Bulkhead (Source: FAA)