

CEN22LA251

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damage Overview (Courtesy of Pilot)



Photograph 2 - Left Side of Engine (Courtesy of Pilot)