

Carburetor Icing Probability Graph – CEN22LA283

Airplane: Amateur-built Osprey II

Engine: Lycoming O-320-E2D

Fuel: 100 LL

Accident Date: 6/24/2022

Accident Location: Bulverde, TX

Accident Time: 0848 CDT

Weather: METAR KSAT 241351Z 22007KT 10SM FEW100
FEW250 27/21 A2999 RMK AO2 SLP135 T02720211=

Celsius to Fahrenheit Conversion:

Temperature, 27° C = 80° F

Dew Point, 21° C = 70° F

Source: Federal Aviation Administration

Special Airworthiness Information Bulletin CE-09-35

Carburetor Icing Prevention

