



Photo 1 – Left side view of the airplane in the field (courtesy of the pilot).



Photo 2 – Right side view of the airplane in the field (courtesy of the pilot).



Photo 3 – View of the airplane in the hangar after it was recovered from the field.



Photo 4 – View of the substantial damage sustained to the right side engine mount.




Photo 5 – View of the substantial damage sustained to the area behind the firewall and to the lower fuselage.



Photo 6 – View of the substantial damage sustained to the left side engine mount.



Photo 7 – View of the air box removed from the engine.



Photo 8 – View of the throttle body with the air box removed, showing foreign object debris lodged in the throttle body.



Photo 9 – View of the throttle body once the foreign object debris was removed.



Photo 10 – View of the foreign object debris removed from the throttle body.