




Photo 1 – No. 5 Cylinder and Rocker Arm (photograph provided by airplane owner)



Photo 2 – End of Push Rod (photograph provided by airplane owner)




Photo 3 - End of Push Rod (photograph provided by airplane owner)



Photo 4 – Right Wing Damage (photograph provided by airplane owner)