

CEN22LA318

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Wreckage Overview (Courtesy of FAA)



Photograph 2 - Main Rotor Mast Hub (Courtesy of FAA)



Photograph 3 - Fractured Rotor Hub (Courtesy of FAA)



Photograph 4 - Main Rotor Mast Hub (Courtesy of FAA)