



Timothy Sorensen
Sr. Aviation Accident Investigator
Aviation Safety - Central Region

Date: February 21, 2023
Subject: CEN22LA330 - Wardsville, Missouri
Contact: Ron Pate - Pilot/Owner

Mr. Pate reported that the oil filter was not replaced at the time of the most recent engine oil change. He noted that the alignment marks on the filter adapter were still matched up. He did not observe any indication that the adapter was loose at that time.

Mr. Pate stated that he was not aware of the previously issued AD or service bulletins related to the oil filter adapter.

----- *end of summary* -----