



Photo 1 – View of the substantial damage sustained to the right wing at the accident site (courtesy of the Federal Aviation Administration).



Photo 2 – View of the substantial damage sustained to the fuselage at the accident site (courtesy of the Federal Aviation Administration).



Photo 3 – View of the fuel tank cap at the accident site (courtesy of the Federal Aviation Administration).




Photo 4 – View of the fuel tank at the accident site, with the fuel tank cap removed (courtesy of the Federal Aviation Administration).




Photo 5 – View of the right side of the airplane at the salvage facility (courtesy of the Federal Aviation Administration).



Photo 6 – View of the left side of the airplane at the salvage facility (courtesy of the Federal Aviation Administration).



Photo 7 – View of the cockpit at the salvage facility (courtesy of the Federal Aviation Administration).



Photo 8 – View of the propeller and the front of the engine at the salvage facility (courtesy of the Federal Aviation Administration).




Photo 9 – View of the right side of the engine at the salvage facility (courtesy of the Federal Aviation Administration).




Photo 10 – View of the left side of the engine at the salvage facility (courtesy of the Federal Aviation Administration).