



Timothy Sorensen
Sr. Aviation Accident Investigator
Aviation Safety - Central Region

Date: October 4, 2022
Subject: CEN22LA403 - Houghton Lake, Michigan
Contact: Joshua Osman - FAA Flight Standards

The pilot informed Insp. Osman that he was alternating fuel from the tanks approximately every 15-20 minutes. During their initial conversation after the accident, the pilot had stated that he changed the fuel tank selector approximately 5 minutes before the engine quit.

----- *end of summary* -----