

CEN22LA421

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at accident site(Courtesy of FAA)



Photograph 2 - Airplane during examination (NTSB Photo)



Photograph 3 - Partially collapsed induction hose (NTSB Photo)