

CEN23FA031

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aerial view of accident site (Courtesy of Nebraska State Patrol)



Photograph 2 - Accident main wreckage (Courtesy of Piper Aircraft, Inc.)



Photograph 3 - Forward fuselage and cockpit (Courtesy of Piper Aircraft, Inc.)



Photograph 4 - Recovered cockpit avionics equipment (Courtesy of Piper Aircraft, Inc.)



Photograph 5 - Propeller assembly (Courtesy of Piper Aircraft, Inc.)



Photograph 6 - Engine compressor and turbine modules (Courtesy of Piper Aircraft, Inc.)