

CEN23FA079

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Debris path viewed from left side of airplane (NTSB Photo)



Photograph 2 - View of airplane from front right (NTSB Photo)



Photograph 3 - Wreckage path (NTSB Photo)



Photograph 4 - View of airplane from right side (NTSB Photo)



Photograph 5 - Engine during on-scene examination (NTSB Photo)



Photograph 6 - View of tail showing oil streaking and sooting (NTSB Photo)



Photograph 7 - View of tail showing oil streaking and sooting (NTSB Photo)