


CEN23FA113


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage at Accident Site



Photograph 2 - Fragment of Propeller Blade Embedded in a Tree Limb



Photograph 3 - Tree Limb Section Showing Propeller Blade Cut



Photograph 4 - Left Engine Power Turbine Section



Photograph 5 - Right Engine Sun Gear and Fractured Propeller Shaft



Photograph 6 - Left Propeller Blade Assembly



Photograph 7 - Right Propeller Blade Assembly