

CEN23F139

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (By NTSB IIC)



Photograph 2 - Aircraft Wreckage (By NTSB IIC)



Photograph 3 - Left Fuel Selector Assembly (By NTSB ICC)



Photograph 4 - Right Fuel Selector Assembly (By NTSB ICC)



Photograph 5 - Right Propeller (By NTSB ICC)



Photograph 6 - Left Propeller (Courtesy of Hartzell Propeller)