

CEN23FA220

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main wreckage



Photograph 2 - Main wreckage



Photograph 3 - Piece of rudder found before impact site



Photograph 4 - Vertical stabilizer found under tree



Photograph 5 - Vertical stabilizer where rudder hinge was torn away



Photograph 6 - Piece of rudder in the tree



Photograph 7 - Vertical stabilizer and rudder