

CEN23FA257

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Scene (Courtesy of LEO)



Photograph 2 - Airplane floats separated from airplane. (Courtesy of LEO)



Photograph 3 -Recovery of accident airplane (Courtesy of LEO)



Photograph 4 - Accident airplane post recovery (Courtesy of LEO)



Photograph 5 - Floats exhibiting significant crush damage (Courtesy of LEO)



Photograph 6 - Instrument Panel



Photograph 7 - Damaged Empennage



Photograph 8 - Propeller Damage



Photograph 9 - Head-on view of the accident airplane