

CEN23FA304

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overview of the accident site.



Photograph 2 - View of the front of the airplane at the accident site.



Photograph 3 - View of the left side of the airplane at the accident site.



Photograph 4 - View of the rear of the airplane at the accident site.



Photograph 5 - View of the right side of the airplane at the accident site.



Photograph 6 - View of the area above the accident site.



Photograph 7 - View of the seats at the accident site.



Photograph 8 - View of the engine at the accident site.



Photograph 9 - View of the propeller at the accident site.



Photograph 10 - View of the cockpit after it was recovered from the accident site.



Photograph 11 - View of the trim tab jackscrew after it was recovered from the accident site (courtesy of Piper Aircraft).



Photograph 12 - View of the trim tab jackscrew, with a ruler for measurement purposes, after it was recovered from the accident site (courtesy of Piper Aircraft).



Photograph 13 - View of the engine after it was recovered from the accident site.



Photograph 14 - View of the propeller after it was recovered from the accident site.



Photograph 15 - View of the airplane after it was recovered from the accident site.