

CEN23FA314

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane Overview



Photograph 2 - Right Engine



Photograph 3 - Left Engine



Photograph 4 - Engine Cockpit Controls



Photograph 5 - Preaccident Animal Nest Right Wing Leading Edge



Photograph 6 - Preaccident Insect Nest around Elevator Trim Jackscrew



Photograph 7 -Airplane Prior to Accident (Courtesy of Airport Staff)




Photograph 8 - Accident Airplane Prior to Purchase (Courtesy of Airport Staff)



Photograph 9 - Right Engine Turbocharger Compressor Section




Photograph 10 - Right Engine Induction Housing Assembly Debris




Photograph 11 - Right Engine Fuel Injectors - X Indicates Full Blockage - / Indicates Partial



Photograph 12 - Preaccident Drained Fuel



Photograph 13 - Unsolicited Message to Ms. Williams from Mr. Reed (Courtesy of Ms. Williams)



Photograph 14 -Right Engine Oil Filter from 2012