

CEN23FA315

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (Courtesy of FAA)



Photograph 2 - Accident site (Courtesy of FAA)



Photograph 3 - Accident site



Photograph 4 - Accident site



Photograph 5 - Left side of inverted airplane



Photograph 6 - Bottom of fuselage



Photograph 7 - Bottom of fuselage



Photograph 8 - Right wing leading edge damage



Photograph 9 - Debris in fuel strainer



Photograph 10 - Debris in fuel strainer



Photograph 11 - Debris in fuel strainer bowl



Photograph 12 - Engine and propeller (Courtesy of Textron Aviation)



Photograph 13 - Oil screen



Photograph 14 - Oil screen housing



Photograph 15 - Oil screen



Photograph 16 - Propeller blade 1 damage



Photograph 17 - Propeller blade 2 damage



Photograph 18 - Propeller blade 2 damage, cambered side



Photograph 19 - Propeller blade 2 damage



Photograph 20 - Headlamp in wreckage



Photograph 21 - Headlamp light on