

CEN23FA352

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right side view of wreckage at accident site (NTSB Photo)



Photograph 2 - Front view of wreckage at accident site (NTSB Photo)



Photograph 3 - Left side view of wreckage at accident site (NTSB Photo)



Photograph 4 - Aft fuselage and tail surfaces at accident site (NTSB Photo)



Photograph 5 - Engine at accident site (NTSB Photo)



Photograph 6 - Crankshaft gear after removal from engine at accident site (NTSB Photo)