

CEN23FA412

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Impact damage noted to fuselage (Courtesy of NTSB)



Photograph 2 - Impact damage and power line impressions (Courtesy of NTSB)



Photograph 3 - Deformation noted to bottom of rudder (Courtesy of Air Tractor)



Photograph 4 - Deformation to bottom of rudder from tailwheel (Courtesy of NTSB)



Photograph 5 - S-type bending noted to propeller blades (Courtesy of NTSB)



Photograph 6 - Torsional deformation noted to exhaust duct case (Courtesy of NTSB)