

CEN23LA014

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right Wing Damage - Front View (Courtesy of FAA)



Photograph 2 - Right Wing Damage - Side View (Courtesy of FAA)