

CEN23LA040

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of Federal Aviation Administration)



Photograph 2 - Number Three Cylinder Head (Courtesy of Federal Aviation Administration)



Photograph 3 - Number Three Cylinder Exhaust Valve (Courtesy of Federal Aviation Administration)



Photograph 4 - Number Three Cylinder Piston Face (Courtesy of Federal Aviation Administration)



Photograph 5 - Number Three Cylinder Piston (Courtesy of Federal Aviation Administration)