



Mitchell Gallo
Senior Aerospace Engineer
Aviation Safety - Central Region

Date: December 12, 2022

Subject: CEN23LA040, Record of Correspondence

Contact: Wilfredo Perez, Aviation Safety Inspector, Federal Aviation Administration

Postaccident examination of the engine revealed that the number three cylinder exhaust valve had failed and resulted in damage to the number three cylinder. At the time of the accident, the engine exceeded the engine manufacturer's time between overhaul period specifications in accordance with Continental Motors Service Information Letter SIL98-9E.