



Photo 1 – Tail of Accident Helicopter (Photo Provided by Survival Flight)



Photo 2 – Tail Rotor Gearbox Mounting Surface (Photo Provided by Survival Flight)



Photo 3 – Landing Skid Removed from Accident Helicopter (Photo Provided by Survival Flight)



Photo 4 – Damaged Tail Rotor (Photo Provided by Survival Flight)




Photo 5 - Tail Rotor Gearbox and Fractured Mounting Surface (Photo Provided by Survival Flight)



Photo 6 – Tail Rotor Driveshaft Coupling Damage (Photo Provided by Survival Flight)



Photo 7 – Electrical Box Struck by Tail Rotor (Photo Provided by Survival Flight)



Photo 8 – Accident Site (Photo Provided by Survival Flight)