



Aaron Sauer
Sr. Air Safety Investigator
Office of Aviation Safety - Central Region

Date: 12/21/2022

Subject: CEN23LA061

Contact: Rotax Engines - Mr. Jordan Paskevich

According to Mr. Paskevich, who examined the airplane and engine with a Federal Aviation Administration inspector at the owner's facility, a functional test of the engine could not be accomplished due to damage to the airplane structure and propeller assembly. No mechanical anomalies were noted with the engine during the examination. With the assistance of a Dynon representative, Mr. Paskevich and the FAA inspector extracted the electronic flight and engine data. The data was forwarded to the NTSB via email.