



Photo 1 – Platform aerial view (Source: Rotorcraft Leasing Company)



Photo 2 – Platform skirting damage (Source: Rotorcraft Leasing Company)



Photo 3 – Platform skirting and light damage (Source: Rotorcraft Leasing Company)



Photo 4 – Platform skirting damage from below (Source: Rotorcraft Leasing Company)



Photo 5 – Platform skirting and light damage (Source: Rotorcraft Leasing Company)



Photo 6 – Helicopter wreckage upside down with floats inflated (Source: Rotorcraft Leasing Company)



Photo 7 – Skid damage (Source: FAA)



Photo 8 – Skid damage (Source: FAA)



Photo 9 – Witness marks (Source: FAA)