



Mitchell Gallo
Senior Aerospace Engineer
Aviation Safety - Central Region

Date: January 30, 2023
Subject: CEN23LA067
Contact: Roland Wright, pilot

Roland Wright stated that the airplane hangar was close to the departure runway and that during the engine runup and takeoff roll, the engine oil temperature gauge indication was "not registering" and he did not remember whether the oil pressure gauge indication was in the normal operating range.