

CEN23LA130

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (FAA Photo)



Photograph 2 - Main Rotor Mast / Blades (FAA Photo)



Photograph 3 - Fuselage / Tail Boom (FAA Photo)



Photograph 4 - Tail Boom / Empennage / Tail Rotor (FAA Photo)



Photograph 5 - Fuselage (NTSB Photo)



Photograph 6 - Fuselage (NTSB Photo)



Photograph 7 - Engine (Lycoming Photo)



Photograph 8 - Engine (Lycoming Photo)