



Photo 1 – View of the front of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 2 – View of the left side of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 3 – View of the right side of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 4 – View of the rear of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 5 – View of the engine and the propeller at the accident site (courtesy of the Federal Aviation Administration).



Photo 6 – View of the front of the airframe during the examination (courtesy of Piper Aircraft).



Photo 7 – View of the left side of the airframe during the examination (courtesy of Piper Aircraft).



Photo 8 – View of the cabin during the examination (courtesy of Piper Aircraft).



Photo 9 – View of the top of the engine during the examination (courtesy of Lycoming Engines).



Photo 10 – View of the left side of the engine during the examination (courtesy of Lycoming Engines).



Photo 11 – View of the right side of the engine during the examination (courtesy of Piper Aircraft).



Photo 12 – View of the propeller during the examination (courtesy of Hartzell Propeller).



Photo 13 – View of the propeller during the examination (courtesy of Hartzell Propeller).



Photo 14 – View of the propeller blades during the examination (courtesy of Hartzell Propeller).