

CEN23LA149

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at accident site (Courtesy of FAA)



Photograph 2 - Engine at accident site (Courtesy of FAA)