

CEN23LA166

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at accident site (Courtesy of FAA)



Photograph 2 - Engine during examination (NTSB Photo)