

CEN23LA170

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane Overview (Courtesy of airplane owner)



Photograph 2 - Broken Left Rudder Cable at the Pulley (Courtesy of Federal Aviation Administration)



Photograph 3 - Rudder Return Springs with Missing Part on Left Spring (Courtesy of Federal Aviation Administration)



Photograph 4 - Left Wing Damage (Courtesy of airplane owner)