

CEN23LA188

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Overview (Photo Source Unknown)



Photograph 2 - Damage to Right Horizontal (Courtesy of FAA)



Photograph 3 - Rocker Arm (Courtesy of FAA)