

CEN23LA200

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Fractured vertical stabilizer (Courtesy of FAA)



Photograph 2 - Fractured vertical stabilizer (Courtesy of FAA)



Photograph 3 - Ground scars from landing (Courtesy of FAA)



Photograph 4 - Separated section of the nose landing gear (Courtesy of FAA)