

Joshua Lindberg

From: Dollahite, Wesley (FAA) [REDACTED]
Sent: Wednesday, June 21, 2023 1:08 PM
To: Lindberg Joshua
Subject: Pics 1

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Josh,
N458TW rudder pedal failure [REDACTED]

Wes Dollahite
Salt Lake City Principal Maint. inspector
Denver Flight Standards District Office
[REDACTED]

The Denver FSDO is dedicated to consistency and standardization and we would value your feedback.
Please provide us your feedback at:
https://www.faa.gov/about/office_org/headquarters_offices/avs/stakeholder_feedback/afx/field/sf_fsdo/

From: Wes Dollahite [REDACTED]
Sent: Wednesday, June 21, 2023 11:56 AM
To: Dollahite, Wesley (FAA) [REDACTED]
Subject: V3





RUDDER PEDAL STOP

REVISION 1 GENERAL MODIFICATIONS 2000-02-24 C.L.

TAILWIND

WITTMAN 2 PLACE - MODEL W-10


DRAWN BY C. LEBLANC EAA 515156
EDITION 1999

TITLE:

RUDDER PEDALS

PAGE:

9



Joshua Lindberg

From: Dollahite, Wesley (FAA) [REDACTED]
Sent: Wednesday, June 21, 2023 7:54 PM
To: Lindberg Joshua
Subject: RE: Pics 2

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Yep Ill text them to ya..looks like when the rudder bar was made using the 3/16 rod there was no penetration of the metals when welded together. No corrosion

[REDACTED]

Wes Dollahite
Salt Lake City Principal Maint. inspector
Denver Flight Standards District Office

[REDACTED]

The Denver FSDO is dedicated to consistency and standardization and we would value your feedback.

Please provide us your feedback at:

https://www.faa.gov/about/office_org/headquarters_offices/avs/stakeholder_feedback/afx/field/sf_fsdo/

From: Lindberg Joshua [REDACTED]
Sent: Wednesday, June 21, 2023 4:49 PM
To: Dollahite, Wesley [REDACTED]
Subject: Re: Pics 2

[REDACTED] Can you text these photos to my [REDACTED] Or were they on a camera? Just need to get the full resolution images.

Could you tell if there was any corrosion on the weld area?

Josh Lindberg
NTSB

From: Dollahite, Wesley [REDACTED]
Sent: Wednesday, June 21, 2023 1:09:08 PM
To: Lindberg Joshua [REDACTED]
Subject: Pics 2

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

N456TW pics 2 ... experimental in Canon City, Co!

Wes Dollahite
Salt Lake City Principal Maint. inspector
Denver Flight Standards District Office



The Denver FSDO is dedicated to consistency and standardization and we would value your feedback.
Please provide us your feedback at:

https://www.faa.gov/about/office_org/headquarters_offices/avs/stakeholder_feedback/afx/field/sf_fsdo/

From: Wes Dollahite [REDACTED]

Sent: Wednesday, June 21, 2023 11:42 AM

To: Dollahite, Wesley (FAA) [REDACTED]

Subject: V











CONFIDENTIALITY NOTICE - THIS E-MAIL TRANSMISSION MAY CONTAIN INFORMATION THAT IS PRIVILEGED, CONFIDENTIAL, PROPRIETARY, SUBJECT TO COPYRIGHT, AND/OR EXEMPT FROM DISCLOSURE UNDER APPLICABLE LAW. IT IS FOR THE USE OF INTENDED RECIPIENTS ONLY. If you are not an intended recipient of this message, please notify the original sender immediately by forwarding what you received and then delete all copies of the correspondence and attachments from your computer system. Any use, distribution, or disclosure of this message by unintended recipients is not authorized and may be unlawful.