

CEN23LA211

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane front right side (Courtesy of pilot)



Photograph 2 - Airplane back right side (Courtesy of pilot)



Photograph 3 - Airplane front side (Courtesy of pilot)



Photograph 4 - Damaged fuselage (Courtesy of pilot)



Photograph 5 - Left and right pedals (Courtesy of pilot)



Photograph 6 - Right side pedals (Courtesy of pilot)



Photograph 7 - Failed weld (Courtesy of FAA)



Photograph 8 - Failed weld (Courtesy of FAA)



Photograph 9 - Failed weld (Courtesy of FAA)



Photograph 10 - Failed weld (Courtesy of FAA)