

CEN23LA217

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Fractured left main landing gear strut housing clevis (Courtesy of the Federal Aviation Administration)



Photograph 2 - Damaged left wing (Courtesy of Federal Aviation Administration)